

SUN BURST

NATURAL ORGANIC GREASE, SLIME & ODOR ELIMINATOR



DESCRIPTION

Sun Burst is a **natural, organic, powerful, solvent degreaser and deodorizer** formulated from the strongest of "Mother Nature's" organic solvents. This material contains distilled citrus plant matter. Its unique, multi-purpose formulation strips grease and heavy oil deposits from virtually any surface. Furthermore, this product **emulsifies instantly in water**, therefore, it **penetrates and liquefies resins and grease**. In addition, it **does not contain any hazardous components** such as benzene orthodichlorobenzene, zylene, toluene III trichloroethylene, or methylene chloride.

BENEFITS - FEATURES

- * Non-fuming
- * Safe on metals
- * Non-corrosive
- * Nonacid
- * No petroleum distilled
- * No alkalis
- * Biodegradable
- * Does not leave a film
- * USDA authorized

ADVANTAGES

- * Cuts through grease build-up
- * Controls odors in problem areas
- * Removes tar, asphalt, & bitumen

WHERE TO USE

- * Drains
- * Septic Tanks
- * Parts Washer
- * Pumping Stations
- * Ovens
- * Soap Scum
- * Grease Traps
- * Dip Tanks
- * Sewer Lines
- * White Walls
- * Tire Marks

RECOMMENDED FOR

- * Schools
- * Offices
- * Automotive Dealers
- * Hotels/Motels
- * Restaurants
- * Bowling Alleys
- * Foundries
- * Hospitals
- * Airports
- * Nursing Homes

DIRECTIONS

Although Sun Burst is safe to use on most plastic and painted surfaces, be sure to pretest before using.

Grease Build-Up - Mix up to 4 to 10 ounces to one gallon warm water in a sprayer or bucket. Spray, wipe, or mop onto greasy equipment, floors, and walls. Allow to work for 5 minutes. Rinse with clean water. The grease is dissolved.

Drains - To open drains clogged by grease, slimes, and soap deposits, Pour 4 to 8 ounces into drain. Allow to stand one hour. Then, flush with hot tap water.

For garbage disposals, allow to stand 5 to 10 minutes. Then, flush with hot water.

Grease Traps - Septic Tanks - To keep lines open, mix 4 to 8 ounces of Sun Burst to one gallon of water. Pour into drain closest to grease trap or septic tank. Allow to stand one hour. Flush with hot tap water. Maintain grease traps 2 to 4 times a week.

Dip Tanks-Parts Washer - Sun Burst may be used as is or mixed with up to 5 parts mineral spirits to effectively dissolve grease and oils. Allow to remain in solution 10 minutes. Hose off with water.

Motor and Parts Cleaning - Spray Sun Burst onto parts and/or motors using a Grime Blaster. Allow to stand 5 to 10 minutes. Rinse with water through a Grime Blaster. May be mixed with 5 parts water or mineral spirits to one part Sun Burst.

Odor Control - Mix 2 to 10 ounces of Sun Burst to one gallon of cold water in sprayer. Spray odor problem areas such as rubbish piles, dumpsters, & garbage cans. Sun burst destroys odors and eliminates source for breeding of maggots in garbage areas. Spraying landfills and rubbish piles will keep birds away.

SPECIFICATIONS

Fragrance.....Citrus
Color.....Orange
pH.....N/A
Shelf life.....1 yr. min.
Flash point.....125°F

Another Exclusive Product of

ULTRA-CHEM INC.

Kansas City - Phoenix 800-451-0726

